

Safety Issue Type: Recalls

October 13 2025 NHTSA Campaign Number: 25V695000

Rearview Camera Image May Not Display

A rearview camera that fails to properly display an image can reduce the driver’s view behind the vehicle, increasing the risk of a crash.

NHTSA Campaign Number 25V695000

Manufacturer Ford Motor Company

Components BACK OVER PREVENTION

Potential Number of Units Affected 1448655

Summary

Ford Motor Company (Ford) is recalling certain 2015-2019 Flex, 2015 Explorer, Lincoln MKT, Lincoln MKZ, 2015-2016 C-Max, Escape, Taurus, 2016 Fusion, 2018-2019 Taurus, 2019 Lincoln MKT, Fiesta, and 2020 Mustang vehicles. The rearview camera may display a distorted, intermittent, or blank image when the vehicle is in reverse.

Remedy

Dealers will inspect and replace the rearview camera as necessary, free of charge. Interim letters, notifying owners of the safety risk, are expected to be mailed in October 2025. Additional letters will be sent once the final remedy is available, anticipated June 2026. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25SA9. Vehicle Identification Numbers (VINs) involved in this recall became searchable on NHTSA.gov on October 14, 2025.

Notes

Affected Products (20)

Vehicle

MAKE	MODEL	YEAR
FORD	C-MAX	2015-2016
FORD	ESCAPE	2015-2016
FORD	EXPLORER	2015
FORD	FIESTA	2019
FORD	FLEX	2015-2019
FORD	FUSION	2016
FORD	MUSTANG	2020
FORD	TAURUS	2015-2016, 2018-2019
LINCOLN	MKT	2015, 2019
LINCOLN	MKZ	2015

Associated Documents (3)

Recall 573 Report

RCLRPT-25V695-4297.pdf 0.803KB

<https://static.nhtsa.gov/odi/rcl/2025/RCLRPT-25V695-4297.pdf>

Notice to Dealers

RCMN-25V695-6489.pdf 0.036KB

<https://static.nhtsa.gov/odi/rcl/2025/RCMN-25V695-6489.pdf>

RCAK - Recall Acknowledgement

RCAK-25V695-0117.pdf 0.321KB

<https://static.nhtsa.gov/odi/rcl/2025/RCAK-25V695-0117.pdf>